


Caption: Measured drawing and elevations of Barn 1 at No. 20-22 Buckingham Street, Pitt Town

Copyright Owner: Graham Edds & Associates



Caption: Measured drawing and elevations of Barn 2 at No. 20-22 Buckingham Street, Pitt Town

Copyright Owner: Graham Edds & Associates

M DETAILS	
ME Single Storey Town Barn with Skillion and Mezzanine	
DRESS 26A Buckingham Street, Pitt Town	
RISH Pitt Town	
T/DP Lot 1 DP 1180284	
I No. 1743106	
ISTING HERITAGE Yes- Item I292 (Heritage Item No. 1740016- listed as 26 Buckingl	nam
M? Street, Pitt Town)	
COMMENDED MANAGEMENT	
ANAGEMENT Recommend for State heritage listing	
MMARY Retain local heritage listing	
M CLASSIFICATION	
M TYPE Built	
M GROUP Farming and Grazing	
M CATEGORY Barn	
SCRIPTION	
RCA Y	
RIOD Late 19 <sup>th</sup> century	
ODIFICATION/DATES	
RRENT USE Vacant	
RMER USE Barn	
CATION ON SITE: Close to street frontage on otherwise vacant site on north-west	ern
fringe of Pitt Town.	
SCRIPTION	
AIN BARN STRUCTURE   Large single-storey barn 12 x 6.5m on plan with round posts up	to
eaves level (4.8m high) mortised and tenoned to square longitu	dinal
beams, with round cross beams.	
Condition: Moderate	
Date: late 19 <sup>th</sup> century	
D. OF BAYS Four	
OOF STRUCTURE Round rafters at close centres with sawn battens for iron and dis	agonal
wind bracing.	. 0 -
Condition: Moderate	
Date: late 19 <sup>th</sup> century	
FT Loft in skillion only supported on round beams let into sides of p	oosts
with dovetail joints.	
Condition:	
Date:	
ILLION 1 Side skillion along eastern side of barn with loft. Wall between s	killion
and main barn and internal partition clad in vertical slabs with	
intermediate framing at upper level which probably supported	
horizontal spaced slats.	
nonzontal spacea stats.	
Condition: Moderate	
·	
Condition: Moderate	
Condition: Moderate Date: late 19 <sup>th</sup> century.	

WALL CLADDING	Vertical slabs up to half height then spaced timber horizontal slats
	fixed to light intermediate framing. This remains intact on north
	elevation. Wall cladding to skillion is two levels of vertical slabs.
	Condition: Poor
	Date: Late 19 <sup>th</sup> century
OPENINGS	West side of main barn has 3 open bays with gudgeon hinges as
	evidence of doors. Single doors to stable and chaff room on east side
	of skillion.
FLOORING (GROUND)	Southern half of barn had timber ground floor. Remains are stacked in
	barn.
FLOORING (LOFT)	Loose timber boarding.
FLOORING (SKILLION)	Not known
INTERNAL STRUCTURE	Remains of dwarf posts, beams and joists ground floor structure.
OTHER (Fixings?)	Cross beams jointed to longitudinal beams with iron straps and bolts
CURRENT USE	Disused
CHANGES FROM 2010?	Deterioration
HISTORY	

No. 26A Buckingham Street, Pitt Town is located on part of a 60 acre grant (Portion 52 Parish Pitt Town) made to John Benn, ex-convict, in 1803. Benn owned various property throughout the Hawkesbury as well as in Sydney. John Benn's real name was John Venman and following his death in c1815, a series of claims were made against his lands by his wife and relatives in England.

Christopher Watkin May made a claim to the Court of Claims commissioners for 2 roods 28 perches bounded by Chatham and Buckingham Streets Pitt Town, which had been promised to his father, Lawrence May. The claim was accepted and the land was granted to Christopher Watkin May on 14 July 1862. Christopher Watkin May, Pitt Town Bottoms, farmer conveyed the land to Charles Emanuel Higgins, Pitt Town, farmer for £120 on 1 February 1879.

No building was shown in this position on any of the Crown surveys of Pitt Town of 1828, 1848 and 1872, indicating that the barn was constructed in the late 19<sup>th</sup> century, post 1872. Aerial photographs of the 1970s show the property as semi-rural.

REFERENCES	New South Wales Government Gazette, 8 Oct 1861 p 2128
	Old System Deed, No 252 Bk 189
	"Law Intelligence", The Sydney Heritage, Monday 24 <sup>th</sup> June 1833, p. 2

## STATEMENT OF SIGNIFICANCE

The town barn at No. 26A Buckingham Street, Pitt Town is of historical significance as a rare, surviving late 19th century timber framed barn of relatively high integrity. Located on a vacant allotment on the northern outskirts of Pitt Town, the barn is highly visible in the streetscape and makes a strong contribution to the historical character of Buckingham Street and Pitt Town. Located on part of a 60 acre grant made to ex-convict John Benn in 1803, the town barn is evidence of the long term agricultural of the land from the early 19th century through to the mid to late 20<sup>th</sup> century.

As a town barn, the building would have been used in association with farm lands located outside of the town of Pitt Town, emphasising the continued importance of agriculture in the district well into the 20<sup>th</sup> century. In its overall form and configuration, it is a representative example of an historic timber framed barn type found throughout the Hawkesbury City local government area.


The single storey barn is of technical significance for retaining evidence of its late 19th century construction date including round posts mortised and tenoned to square longitudinal beams, with round cross beams, round rafters with battens for iron and diagonal wind bracing, dovetail joints

to post in loft, two levels of slabs to skillion, horizontal slats to upper level of main barn and gudgeon hinges (doors removed). Although currently not in use, the barn continues to have the potential to provide further information into late 19<sup>th</sup> century farming methods, the relationship between the town barn and other agricultural lands, as well as the continuity of use of historic agricultural buildings into the 20th century.

agricultural buildings into t	ne 20th century.
ASSESSED SIGNIFICANCE TYPE	State
CRITERIA A) HISTORICAL	The barn at No. 26A Buckingham Street, Pitt Town is of historical significance as a surviving late 19 <sup>th</sup> century town barn that provides evidence of the long-term agricultural use of the land from the late 18 <sup>th</sup> century through to the 20 <sup>th</sup> century.  As a town barn, the building would have been used in association with farm lands located outside of the town of Windsor, emphasising the continued importance of agriculture in the district well into the 20 <sup>th</sup> century.  Meets the criterion on a State level
CRITERIA B) HISTORICAL ASSOCIATION	The town barn at No. 26A Buckingham Street, Pitt Town has some historical associations with ex convict John Benn, who received a 60 acre grant of land in 1803, on which the barn is now located; and with Charles Emanuel Higgins, who appears to have built the barn in the 1880s (or later).  Meets the criterion on a Local level
CRITERIA C) AESTHETIC/TECHNICAL	Located in an undeveloped allotment, the large barn is highly visible in Buckingham Street and makes a strong contribution to the historical character of Buckingham Street and Pitt Town.  The single storey barn is of technical significance for retaining evidence of its late 19 <sup>th</sup> century construction date including round posts mortised and tenoned to square longitudinal beams, with round cross beams, round rafters with battens for iron and diagonal wind bracing, dovetail joints to post in loft, two levels of slabs to skillion, horizontal slats to upper level of main barn and gudgeon hinges (doors removed).  Meets the criterion on a State level
CRITERIA D) SOCIAL/CULTURAL	The historic barns of the Hawkesbury district are appreciated by the local community and others, being symbolic of the history of the agricultural development of the region, as evidenced by the numerous exhibitions, artworks, historical tours, heritage studies and heritage listings associated with these building types.  Meets the criterion on a Local level
CRITERIA E) RESEARCH POTENTIAL	The barn No. 26A Buckingham Street, Pitt Town has the potential to provide further information into late 19 <sup>th</sup> century farming methods and the relationship between the town barn and other agricultural lands, as well as the continuity of use of historic agricultural buildings into the 21 <sup>st</sup> century.  Meets the criterion on a Local level
CRITERIA F) RARITY	As a surviving late 19 <sup>th</sup> century town barn of relatively high integrity, the barn at 26A Buckingham Street, Pitt Town is considered to be rare within the context of the Hawkesbury City local government area. <i>Meets the criterion on a State level</i>

CRITERIA G)	The barn at No. 26A Buckingham Street, Pitt Town is representative of
REPRESENTATIVE	the long history of agricultural development within the Hawkesbury
	area, which commenced in the late 18 <sup>th</sup> century and continues today.
	The basic form of the barn with gabled roof, loft, skillion and timber
	slab wall cladding is representative of the typical form of barn found
	throughout the district.
	Meets the criterion on a Local level
INTEGRITY/INTACTNESS	Moderate to High

# **IMAGES**



Caption: Barn at No. 26A Buckingham Street, Pitt Town Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023




Caption: Barn at No. 26A Buckingham Street, Pitt Town

(interior view)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023



Copyright Owner: Graham Edds & Associates

NAME  Single Storey Town Barn with Loft and Skillion  ADDRESS  4-8 Chatham Street, Pitt Town  LOCAL GOVT AREA  Hawkesbury  PARISH  Pitt Town  LOT/DP  Lot 1 DP 785736  SHI No.  1743104  EXISTING HERITAGE ITEM?  Yes- Item 1293 (Heritage Item No. 1740017)  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY  Retain as local heritage item.  ITEM CLASSIFICATION  ITEM GROUP  ITEM GROUP  Farming and Grazing  ITEM CATEGORY  Barn  DESCRIPTION  CIRCA  Y  PERIOD  Mid 19 <sup>th</sup> century  MODIFICATION/DATES  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected  Condition: Good  Date: Recent  SKILLION 1  OPEN Skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ITEM DETAILS	
Single Storey Town Barn with Loft and Skillion  ADDRESS  4-8 Chatham Street, Pitt Town  LOCAL GOVT AREA  Hawkesbury  PARISH  PIT Town  LOT/DP  Lot 1 DP 785736  SHI No.  1743104  EXISTING HERITAGE ITEM?  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY  Retain as local heritage item.  ITEM CLASSIFICATION  ITEM CLASSIFICATION  ITEM GROUP  ITEM GROUP  ITEM GROUP  ITEM GROUP  ITEM GROUP  ITEM GROUP  ITEM CATEGORY  Barn  DESCRIPTION  CIRCA  Y  PERIOD  Mod 19 <sup>th</sup> century  MODIFICATION/DATES  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected  Condition: Good  Date: Recent  Not inspected  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	-	
LOCAL GOVT AREA  PARISH  LOT/DP  Lot 1 DP 785736  SHI No.  1743104  EXISTING HERITAGE ITEM? Yes- Item I293 (Heritage Item No. 1740017)  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY  Mot recommended for State heritage listing.  Retain as local heritage item.  ITEM CLASSIFICATION  ITEM GROUP  ITEM GROUP  ITEM GROUP  ITEM CATEGORY  Barn  DESCRIPTION  CIRCA  Y  PERIOD  Mid 19 <sup>th</sup> century  MODIFICATION/DATES  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected  Condition: Good  Date: Rid-19 <sup>th</sup> century with recent conservation on renovation  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	IVAIVIE	Single Storey Town Barn with Loft and Skillion
PARISH Pitt Town  LOT/DP Lot 1 DP 785736  SHI No. 1743104  EXISTING HERITAGE ITEM? Yes- Item I293 (Heritage Item No. 1740017)  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY Not recommended for State heritage listing.  Retain as local heritage item.  ITEM CLASSIFICATION  ITEM TYPE Built  ITEM GROUP Farming and Grazing  ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street.  Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°.  Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts.  Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ADDRESS	4-8 Chatham Street, Pitt Town
LOT/DP Lot 1 DP 785736 SHI No. 1743104 EXISTING HERITAGE ITEM? Yes- Item I293 (Heritage Item No. 1740017) RECOMMENDED MANAGEMENT MANAGEMENT SUMMARY Not recommended for State heritage listing. Retain as local heritage item.  ITEM CLASSIFICATION ITEM TYPE Built ITEM GROUP Farming and Grazing ITEM CATEGORY Barn DESCRIPTION CIRCA Y PERIOD Mid 19 <sup>th</sup> century MODIFICATION/DATES Restored and adapted in 1990s CURRENT USE Garage and carport with residence/guest room (?) above FORMER USE Barn LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	LOCAL GOVT AREA	Hawkesbury
SHI No. 1743104  EXISTING HERITAGE ITEM? Yes- Item 1293 (Heritage Item No. 1740017)  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY Retain as local heritage item.  ITEM CLASSIFICATION  ITEM CLASSIFICATION  ITEM GROUP Farming and Grazing  ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	PARISH	Pitt Town
EXISTING HERITAGE ITEM? Yes- Item I293 (Heritage Item No. 1740017)  RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY Not recommended for State heritage listing. Retain as local heritage item.  ITEM CLASSIFICATION  ITEM TYPE Built Farming and Grazing  ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	LOT/DP	Lot 1 DP 785736
RECOMMENDED MANAGEMENT  MANAGEMENT SUMMARY  Not recommended for State heritage listing.  Retain as local heritage item.  ITEM CLASSIFICATION  ITEM TYPE  Built  ITEM GROUP  Farming and Grazing  ITEM CATEGORY  Barn  DESCRIPTION  CIRCA  Y  PERIOD  Mid 19 <sup>th</sup> century  MODIFICATION/DATES  Restored and adapted in 1990s  CURRENT USE  Garage and carport with residence/guest room (?) above  FORMER USE  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	SHI No.	1743104
MANAGEMENT SUMMARY Retain as local heritage item.  ITEM CLASSIFICATION  ITEM TYPE Built ITEM GROUP Farming and Grazing ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century MODIFICATION/DATES Garage and carport with residence/guest room (?) above FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	EXISTING HERITAGE ITEM?	Yes- Item I293 (Heritage Item No. 1740017)
Retain as local heritage item.  ITEM CLASSIFICATION  ITEM TYPE Built  ITEM GROUP Farming and Grazing  ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	RECOMMENDED MANAGEM	ENT
ITEM CLASSIFICATION  ITEM TYPE Built  ITEM GROUP Farming and Grazing  ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	MANAGEMENT SUMMARY	Not recommended for State heritage listing.
ITEM TYPE  ITEM GROUP  Farming and Grazing  ITEM CATEGORY  Barn  DESCRIPTION  CIRCA  Y  PERIOD  Mid 19 <sup>th</sup> century  MODIFICATION/DATES  CURRENT USE  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Retain as local heritage item.
ITEM GROUP ITEM CATEGORY Barn  DESCRIPTION  CIRCA Y PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ITEM CLASSIFICATION	
ITEM CATEGORY  DESCRIPTION  CIRCA  Y  PERIOD  Mid 19 <sup>th</sup> century  MODIFICATION/DATES  Restored and adapted in 1990s  CURRENT USE  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ITEM TYPE	Built
CIRCA PERIOD Mid 19 <sup>th</sup> century MODIFICATION/DATES CURRENT USE Garage and carport with residence/guest room (?) above FORMER USE Barn LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ITEM GROUP	Farming and Grazing
CIRCA PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°. Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ITEM CATEGORY	
PERIOD Mid 19 <sup>th</sup> century  MODIFICATION/DATES Restored and adapted in 1990s  CURRENT USE Garage and carport with residence/guest room (?) above  FORMER USE Barn  LOCATION ON SITE: Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE Barn was not inspected internally just from the street.  Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS Three  ROOF STRUCTURE Not inspected internally. Reconstructed at approximately 35°.  Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts.  Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	DESCRIPTION	
MODIFICATION/DATES  CURRENT USE  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	CIRCA	Υ
MODIFICATION/DATES  CURRENT USE  Garage and carport with residence/guest room (?) above  FORMER USE  Barn  LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	PERIOD	Mid 19 <sup>th</sup> century
CURRENT USE  FORMER USE  Barn  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  LOFT  Not inspected  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	MODIFICATION/DATES	•
LOCATION ON SITE:  Close to street at south-west corner of town allotment.  MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  LOFT  Not inspected  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	CURRENT USE	·
MAIN BARN STRUCTURE  Barn was not inspected internally just from the street.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  LOFT  Not inspected  Condition: Good  Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	FORMER USE	
Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°. Condition: Good  LOFT  Not inspected Condition: Good Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	LOCATION ON SITE:	Close to street at south-west corner of town allotment.
Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation  NO. OF BAYS  Three  Not inspected internally. Reconstructed at approximately 35°. Condition: Good  LOFT  Not inspected Condition: Good Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	MAIN BARN STRUCTURE	Barn was not inspected internally just from the street.
NO. OF BAYS  ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  LOFT  Not inspected Condition: Good Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Condition: Good
ROOF STRUCTURE  Not inspected internally. Reconstructed at approximately 35°.  Condition: Good  Not inspected Condition: Good Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation
Condition: Good  LOFT Not inspected Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	NO. OF BAYS	Three
Condition: Good  LOFT Not inspected Condition: Good Date: Recent  SKILLION 1 Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	ROOF STRUCTURE	Not inspected internally. Reconstructed at approximately 35°.
Condition: Good Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Condition: Good
Date: Recent  SKILLION 1  Open skillion along eastern side supported on round posts. Condition: Good Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	LOFT	Not inspected
SKILLION 1 Open skillion along eastern side supported on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Condition: Good
Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		Date: Recent
Condition: Good  Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation	SKILLION 1	Open skillion along eastern side supported on round posts.
		Condition: Good
ROOF CLADDING: Corrugated steel single sheets.		Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation
	ROOF CLADDING:	Corrugated steel single sheets.
Condition: Good	,	Condition: Good
Date: Recent		
WALL CLADDING Vertical timber slabs to loft floor level, weatherboards above.	WALL CLADDING	Vertical timber slabs to loft floor level, weatherboards above.
Condition: Good		
Date: Mid-19 <sup>th</sup> century with recent conservation/ renovation		•
<b>OPENINGS</b> Double garage door at northern end, recent double doors & security grille at loft level.	OPENINGS	Double garage door at northern end, recent double doors & security grille at loft level.
FLOORING (GROUND) Not known	FLOORING (GROUND)	
FLOORING (LOFT) Not known	FLOORING (LOFT)	Not known
FLOORING (SKILLION) Not known	FLOORING (SKILLION)	Not known
INTERNAL STRUCTURE Not known	INTERNAL STRUCTURE	Not known

#### **HISTORY**

This land was shown in the name of C. Tilley on E J H Knapp's plan of 1828, with the rough outline of a building upon it. The site was further shown in the 1843 survey by J. J. Galloway with a dwelling close to the road on the northern part of the lot.

Charles Tilley, butcher of Windsor, died on 2 January 1857, and his property passed to his son also known as Charles Tilley.

On 10 May 1875, Charles Tilley, butcher of Windsor, sold this allotment that he had inherited from his father to Richard Owens for £14.

The survey by surveyor E Arnheim of 1872 showed the land owned and occupied by 'R Owen' with the footprint of the existing barn close to the street alignment.

On 21 September 1923, Albert James Owens, schoolteacher originally of Pitt Town, but then of Cranebrook, sold this allotment to James Davis for £300.

Based on the documentary evidence, it appears that the town barn at 4-8 Chatham Street, Pitt Town was constructed pre 1872 and is associated with Charles Tilley Snr or Jnr.

REFERENCES	P.628B Crown plan
	P.1.522 Crown Plan
	P.3.857 Crown plan
	Old System Deed, No 573 Bk 152
	Old System Deed, No 68 Bk 1320

#### STATEMENT OF SIGNIFICANCE

The town barn at No. 4-8 Chatham Street, Pitt Town Catherine Street, Windsor is of historical significance as a surviving mid 19<sup>th</sup> century timber framed town barn, associated with an historic residence and shop that was owned by Charles Tilley and his son Charles Tilley, both butchers from the 1820s to the 1870s. Although restored and adapted, the town barn is considered to be rare within the Hawkesbury LGA.

Located on the street, and together with the adjacent residence and shop, the town barn makes a strong contribution to the historical character of Pitt Town. In its overall form and configuration, it is a representative example of an historic timber framed barn type found throughout the Hawkesbury City local government area.

The barn continues to have the potential to provide further information into mid 19<sup>th</sup> century farming methods, the relationship between the town barn and other agricultural lands, as well as the continuity of use of historic agricultural buildings into the 21<sup>st</sup> century.

ASSESSED SIGNIFICANCE	Local
TYPE	
CRITERIA A) HISTORICAL	The barn at No. 4-8 Chatham Street, Pitt Town is of historical
	significance as a surviving mid 19 <sup>th</sup> century town barn associated
	with an historic residence and shop, which enhances its significance.
	Meets the criterion on a Local level.
CRITERIA B) HISTORICAL	The town barn has historical associations with Charles Tilley,
ASSOCIATION	butcher and his son, also Charles Tilley, a butcher, who owned the
	property from the late 1820s through to the 1870s and it is assumed
	operated their butcher's shop from the property.
	Meets the criterion on a Local level.
CRITERIA C)	Although restored and adapted, the town barn is located on the
AESTHETIC/TECHNICAL	street frontage and together with the adjacent historic residence
	and shop, makes a strong contribution to the historical character of
	the town of Pitt Town.
	Meets the criterion on a Local level.

CRITERIA D)	The historic barns of the Hawkesbury district are appreciated by the
SOCIAL/CULTURAL	local community and others, being symbolic of the history of the
SOCIAL/COLI ONAL	agricultural development of the region, as evidenced by the
	,
	numerous exhibitions, artworks, historical tours, heritage studies
	and heritage listings associated with these building types.
	Meets the criterion on a Local level.
CRITERIA E) RESEARCH	The barn at No. 4-8 Chatham Street, Pitt Town, has the potential to
POTENTIAL	provide further information into mid 19 <sup>th</sup> century farming methods
	and the relationship between the town barn and other agricultural
	lands, as well as the continuity of use of historic agricultural
	buildings into the 21 <sup>st</sup> century.
	Meets the criterion on a Local level.
CRITERIA F) RARITY	Although restored and adapted, the barn at No. 4-8 Chatham Street,
	Pitt Town, is considered to be rare as a surviving town barn, within
	the context of the Hawkesbury City local government area.
	Meets the criterion on a Local level.
CRITERIA G)	The town barn at No. 4-8 Chatham Street, Pitt Town is
REPRESENTATIVE	representative of the long history of agricultural development
	within the Hawkesbury area, which commenced in the late 18 <sup>th</sup>
	century and continues today.
	The basic form of the barn with gabled roof, loft, skillion and slab
	wall cladding is representative of the typical form of barn found
	throughout the district.
	Meets the criterion on a Local level.
INTEGRITY/INTACTNESS	Moderate (assumed)

# **IMAGES**



Caption: The town barn at No. 4-8 Chatham Street, Pitt Town Photographer: S. Johnson

Copyright Owner: Lucas Stapleton Johnson &

Partners

Date: May 2023




Caption: The town barn at No. 4-8 Chatham Street, Pitt Town Photographer: S. Johnson

Copyright Owner: Lucas Stapleton Johnson &

Issue: March 2024

Partners



Caption: Measured drawing and elevations of town barn at No. 4-8 Chatham Street, Pitt Town

Copyright Owner: Graham Edds & Associates

ITEMA DETAILS	
ITEM DETAILS	Cincle Chause Clab Wardish on Building
NAME	Single Storey Slab Workshop Building
OTHER/FORMER NAMES	Huxley's Blacksmith Shop (former)
ADDRESS	292 Pitt Town Road, Pitt Town
LOCAL GOVT AREA	Hawkesbury
PARISH	Pitt Town
LOT/DP	Lot 11 DP 10192
SHI No.	1743107
EXISTING HERITAGE ITEM?	Yes- Item I304 (Heritage Item No. 1740026)
RECOMMENDED MANAGEM	IENT
MANAGEMENT SUMMARY	Not recommended for State heritage listing
	Retain as local heritage item
ITEM CLASSIFICATION	
ITEM TYPE	Built
ITEM GROUP	Farming and Grazing
ITEM CATEGORY	Blacksmithy
DESCRIPTION	
CIRCA	Υ
PERIOD	Late 19 <sup>th</sup> century
CURRENT USE	Vacant
FORMER USE	Blacksmith shop
LOCATION ON SITE:	Alongside the main road to Pitt Town and approximately 1.3km to the
	south of the town centre.
DESCRIPTION FORMER BLAC	CKSMITHS SHOP
MAIN STRUCTURE	Mixture of round and square posts support langitudinal square hoams
IVIAIN STRUCTURE	Mixture of round and square posts support longitudinal square beams (eastern beam reinforced with round beam under). Many posts are
	missing, fallen or dislodged.
	Condition: Poor – western and southern sides are structurally
	unstable.
	Date: late 19 <sup>th</sup> century
NO OF PAVE	·
NO. OF BAYS	Six
ROOF STRUCTURE	Roof pitch is approximately 30°. Sawn rafters (smoke blackened) at
	close centres with widely spaced battens for iron.
	Condition: Poor
	Date: late 19 <sup>th</sup> century
LOFT	N/A
SKILLION 1	Eastern skillion is still intact with some remaining slabs and a vertical
	storage rack formed between two closely spaced posts halfway along
	the building.
	Condition: Poor
	Date: late 19 <sup>th</sup> century
SKILLION 2	Western skillion is dilapidated almost to the point of collapse but
	retains some evidence of early detailing in post and beam joints
	Condition: Poor
	Date: post and beam
ROOF CLADDING:	Corrugated iron
	Condition: Poor
	Date: Unknown
	-

WALL CLADDING	Approximately 25% remnant vertical timber slabs remain in situ. The rest of the wall cladding is vertical corrugated iron.  Condition: Poor  Date: late 19 <sup>th</sup> century
OPENINGS	Doors on all sides
FLOORING (GROUND)	Concrete slab
FLOORING (LOFT)	N/A
FLOORING (SKILLION)	Concrete slab
INTERNAL STRUCTURE	Remains of bench and internal water trough for quenching iron.
OTHER (Fixings?)	Raised brick hearth still exists in south-east corner and some blacksmith tackle, a storage rack, iron tools, a vice, chains, etc.
CURRENT USE	Disused and unsafe.
CHANGES FROM 2010?	Deterioration.

#### **HISTORY**

History drawn from Inventory Sheet (Item No. 1304, Heritage Item No. 1740026)

No. 292 Pitt Town Road, Pitt Town is located on part of a 125 acre grant (Portion 74, Parish Pitt Town) made to John Palmer, Commissary of NSW in 1804 and a 280 acre grant (Portion 56, Parish Pitt Town) made to Thomas Biggers, ex-convict and overseer for Palmer, in 1804.

This land had been acquired by John McDonald by 1825, and after his death in 1874, it passed to his devisees who held it for many years. The whole of the McDonald Estate was subdivided and put up for auction on 24 March 1920. A "House or blacksmith's shop" was shown on lot 11 on the auction plan.

Lot 11 was transferred to William John Huxley, blacksmith on 15 June 1922 and he held it until it passed to his devisees in 1968 after his death.

Although purchased by William, the property had been tenanted by his parents Samuel and Sarah Huxley from the 1880s and where Samuel Huxley operated his blacksmithy. His brother Thomas Huxley was a coach and buggy builder with shops in Richmond and Windsor. William continued in the family business.

The building was sketched in the late 20<sup>th</sup> century and appears in the publication *Pitt Town and thereabouts*, 1950-1974 by Gifford Eardley.

REFERENCES	RPA 7988; C T 1090 f 221; C T 3355 f 52; Sands, Directory, 1901, p 823;
	DP 57988; Subdivision Plans ML, R8/42.1
	Obituary: Sarah Huxley, Windsor and Richmond Gazette, Friday 16 <sup>th</sup> July
	1920, p 4
	Advertising, Windsor and Richmond Gazette, Saturday 4 June 1890, p. 2
	Article: Death of Mr. Samuel Huxley, Nepean Times, Saturday 23rd
	September 1922, p. 1

#### STATEMENT OF SIGNIFICANCE

The former blacksmith workshop and house at No. 292 Pitt Town, Pitt Town is of historical significance as a rare, surviving late 19<sup>th</sup> century blacksmithy that provides evidence of the long term agricultural use of the land first granted in 1804. The timber framed, slab building is associated with Samuel Huxley who established the blacksmith business in the 1880s and his son William Huxley who continued on into the 20<sup>th</sup> century.

Located close to Pitt Town Road, the former blacksmiths and house, although now dilapidated, was once a notable building appearing in the publication *Pitt Town and thereabouts, 1950-1974* by Gifford Eardley and it continues to make a strong contribution to the historical character of the

agricultural landscape on the	e outskirts of Pitt Town. As a surviving late 19th century slab blacksmith
workshop and former house	, the building is of technical significance and may contain objects and
fittings of note associated wi	ith the historical use of the place as a blacksmithy.
ASSESSED SIGNIFICANCE	Local
TYPE	
CRITERIA A) HISTORICAL	The former blacksmiths workshop and house at No. 292 Pitt Town
	Road, Pitt Town Bottoms is of historical significance as a surviving late
	19 <sup>th</sup> century blacksmithy and as evidence of the long-term agricultural
	use of the land, associated with two large early grants made to John
	Palmer, Commissary of NSW in 1804 and Thomas Biggers, ex-convict
	and overseer for Palmer, in 1804.
	Meets the criterion on a Local level.
CRITERIA B) HISTORICAL	The building has historical associations with the Samuel Huxley, who
ASSOCIATION	established the blacksmiths (together with a house) on the property
	in the 1880s and his son William Huxley who continued on with the
	business and held the property until the late 20 <sup>th</sup> century.
	Meets the criterion on a Local level.
CRITERIA C)	Located close to Pitt Town Road, the former blacksmith building,
AESTHETIC/TECHNICAL	although now dilapidated, was once a notable building appearing in
•	the publication Pitt Town and thereabouts, 1950-1974 by Gifford
	Eardley and it continues to make a strong contribution to the
	historical character of the agricultural landscape on the outskirts of
	Pitt Town.
	As a surviving late 19 <sup>th</sup> century slab blacksmith workshop and former
	house, the building is of technical significance and may contain
	objects and fittings of note associated with the historical use of the
	place as a blacksmithy.
	Meets the criterion on a Local level.
CRITERIA D)	The historic slab buildings of the Hawkesbury district are appreciated
SOCIAL/CULTURAL	by the local community and others, being symbolic of the history of
	the agricultural development of the region, as evidenced by the
	numerous exhibitions, artworks, historical tours, heritage studies and
	heritage listings associated with these building types.
	Meets the criterion on a Local level.
CRITERIA E) RESEARCH	As a surviving late 19 <sup>th</sup> century slab blacksmith workshop and former
POTENTIAL	house, the building has the potential to provide further information
	into late 19th century blacksmithing techniques.
	Meets the criterion on a Local level.
CRITERIA F) RARITY	The building at No. 292 Pitt Town Road, Pitt Town is rare within the
	context of the Hawkesbury City local government area, as a surviving
	late 19 <sup>th</sup> century timber slab blacksmith workshop and house.
	Meets the criterion on a Local level.
CRITERIA G)	The timber framed and slab clad former workshop building at No. 272
REPRESENTATIVE	Pitt Town Road, Pitt Town is representative of the long history of
	agricultural development within the floodplains of the Hawkesbury
	River, which commenced in the late 18 <sup>th</sup> century and continues today.
	Meets the criterion on a Local level.
	Wicets the chieffor on a Local level.

#### **IMAGES**



Caption: Former blacksmith workshop and house at No. 292 Pitt Town Road, Pitt

Town (exterior) Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023



Caption: Former blacksmith workshop and house at No. 292 Pitt Town Road, Pitt Town (exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023




Caption: Brick hearth inside former blacksmith workshop at No. 292 Pitt Town Road,

Pitt Town

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023



Caption: Measured drawing of former blacksmith workshop and house at No. 292 Pitt Town Road,

Pitt Town

Copyright Owner: Graham Edds & Associates

ITEM DETAILS		
NAME	Single Storey Slab Barn with Loft- Demolished	
OTHER/FORMER NAMES	-	
ADDRESS	163 Pitt Town Bottoms Road, Pitt Town Bottoms	
LOCAL GOVT AREA	Hawkesbury	
PARISH	Pitt Town	
LOT/DP	Lot 1 DP 1014860	
SHI No.	1743090	
EXISTING HERITAGE ITEM?	N	
RECOMMENDED MANAGEM	IENT	
MANAGEMENT SUMMARY	Not recommended for State or local listing	
ITEM CLASSIFICATION		
ITEM TYPE	Built	
ITEM GROUP	Farming and Grazing	
ITEM CATEGORY	Barn	
DESCRIPTION		
CIRCA	Υ	
PERIOD	Late 18 <sup>th</sup> to mid 19 <sup>th</sup> century	
MODIFICATION/DATES	1991-2009 The owners advised that during a wind storm	
	approximately 15 years ago the roof blew off. He has placed sheet	
	metal over the former loft floor to provide some weather protection	
	and the barn is still in use [2009 inventory sheet]	
CURRENT USE	N/A- Demolished	
FORMER USE	Barn	
INTEGRITY/INTACTNESS	Demolished	

2023: Barn has been demolished

## [2010 inventory sheet]

The physical description below is an extract from the 'Pitt Town Slab Barn Study', 1991, by Graham Edds and Associates. This 2009 study has recorded changes/deterioration within the modification date field.

#### Description 1991:

Single storey slab barn with loft having external door. Enclosed on three sides with later skillion additions using original slabs to loft floor level. Horizontal splayed boarding above slabs and at gable ends. Central area of barn 9.5m x 5.2m. The main roof is gabled clad with corrugated iron. Located on land below the 1 in 100 year floor level.

#### Structure:

Post and beam with posts set into ground extending into loft space with second top plate providing framework for roof structure. Timber rounds used exclusively. For post structure, loft joists and roof frame. Posts set in ground with spacing generally 1.5m

### **HISTORY**

James Ruse (first emancipist to be granted land, known as Experiment Farm Cottage, Harris Park) was granted 30 acres on the east side of the River Hawkesbury in the district of Mulgrave Place to be known as Ruse Farm on 3 November 1794. On 19 March 1798, James Ruse conveyed Ruse Farm to John Stogdell for £300.

Judge Advocate David Collins claimed in his history of the early years of the colony that Ruse sold his farm for £40. The legal deed, which Collins himself registered as the Judge Advocate, showed that this was incorrect. Jan Barkley-Jack has argued that Collins libelled Ruse and his neighbour Charles Williams as examples of the unreliability of ex-convict settlers.

The history of Ruse's grant is complicated by gaps in the registered legal title but the following has been compiled from reliable sources.

By 1814, John Palmer was the owner of Ruse Farm. On 9 August 1814, John Palmer, of Parramatta, esquire conveyed various parcels of land for £14,489/12/0 to William Fairley, Allan Gilmore, John Hutchinson and David Clarke, all of Calcutta Fort, Province of Bengal, East India, merchants and partners in Fairley Gilmore & Co and John Gilmore and William Wilson, partners in the firms of John Gilmore and Co. Ruse's 30 acre farm was one of the properties. On 13 October 1814, those partners conveyed several parcels of land to John Benn, of Pitt Town, settler including Ruse's 30 acres. Benn leased part of the farm to Thomas Gilberthorpe, settler of Pitt Town including Ruse's farm on 4 September 1815 from 1 January 1816 for 14 years at £200 per annum. The lease included 'the House, Houses, Out buildings & Buildings, Barns Erections, Fences, Fixtures, Rights common rights and appurtenances of every kind'.

An auction of land was advertised for 13 September 1817 to be held by the Provost Marshall, in the case of Roberts versus the administrator of Benn. It included 30 acres, Ruse Farm. A later advertisement appeared on 21 August 1819 offering farms for sale by Mr Bevan for Richard Jones as agent for the heir of the late John Benn including 30 acres granted to James Ruse. By 1829, John Venman held Ruse's grant as the brother and heir of William Venman, also known as John Benn. On 6 June 1829, he conveyed Ruse's Farm to a trustee for the benefit of John Perkins and his wife, Mary, for £600. Years later, on 13 July 1861, John Perkins swore a statutory declaration that he had received the rents of three farms, including James Ruse's since 1830. John Perkins, originally of Sydney, but then of Stepney Green in County Middlesex, England esquire conveyed 30 acres known as Ruse Farm plus 30 acres known as Williams Farm to John Hannabus, Pitt Town, farmer on 16 April 1861 for £3,000. John Hannabus died on 28 August 1888. On 28 October 1921, a deed of partition of the lands of John Hannabus amongst his heirs included a map showing the division of the land. It also showed existing the buildings on the property.

a map showing the division of the land. It also showed existing the ballangs on the property.		
REFERENCES	Grants Vol 1 No 104	
	Old Register Volume 1 page 30 no 143	
	Jan Barkley-Jack, Hawkesbury Settlement Revealed, p 81	
	John Benn, Lease, Mitchell Library Doc Ab 51	
	Sydney Gazette, 6 Sept 1817, p 2; 21 Aug 1819, p 3; 21 Aug 1819, p 3	
	Old System Deed, No 261 Bk 77	
	Old System Deed, No 560 No 1244	

ITEM DETAILS			
	Consular of Two Clab Down with Chillians		
NAME	Complex of Two Slab Barns with Skillions		
ADDRESS	231 Pitt Town Bottoms Road, Pitt Town Bottoms		
LOCAL GOVT AREA	Hawkesbury		
PARISH	Pitt Town		
LOT/DP	Lot 21 DP 730868		
SHI No.	1743091		
EXISTING HERITAGE	Y- I461 (Heritage Item no. 1740027)		
ITEM?			
RECOMMENDED MANAGE	MENT		
MANAGEMENT	Not recommended for State heritage listing.		
SUMMARY	Retain as local heritage item.		
ITEM CLASSIFICATION			
ITEM TYPE	Built		
ITEM GROUP	Farming and Grazing		
ITEM CATEGORY	Barn		
DESCRIPTION			
CIRCA	Υ		
PERIOD	Barn A: Mid-19 <sup>th</sup> century but recently extensively renovated		
	Barn B: Late-19 <sup>th</sup> early 20 <sup>th</sup> century		
CURRENT USE	Barn A: Entertainment area		
	Barn B: vacant		
FORMER USE	Barns		
LOCATION ON SITE:	The two barns are arranged in an L-shape to the south of the house		
	and close to the eastern bank of the Hawkesbury River.		
DESCRIPTION BARN A	,		
2 20 01111 11011 211111111			
	Two-storey barn orientated north-south with tall side skillion to west		
MAIN BARN STRUCTURE	Two-storey barn orientated north-south with tall side skillion to west and end skillion to south. It has been extensively repaired and		
	and end skillion to south. It has been extensively repaired and		
	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m		
	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of		
	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.		
	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good		
MAIN BARN STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.		
MAIN BARN STRUCTURE  NO. OF BAYS	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five		
MAIN BARN STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.		
MAIN BARN STRUCTURE  NO. OF BAYS	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?		
MAIN BARN STRUCTURE  NO. OF BAYS	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.		
NO. OF BAYS ROOF STRUCTURE  LOFT	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.  Condition: Good		
NO. OF BAYS ROOF STRUCTURE  LOFT  SKILLION 1	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19th century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19th century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.  Condition: Good  Date: Mid-19th century but recently extensively renovated.		
NO. OF BAYS ROOF STRUCTURE	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  End skillion with lower floor level. Sawn rafters supported on beam		
NO. OF BAYS ROOF STRUCTURE  LOFT  SKILLION 1	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  End skillion with lower floor level. Sawn rafters supported on beam bolted to main posts.		
NO. OF BAYS ROOF STRUCTURE  LOFT  SKILLION 1	and end skillion to south. It has been extensively repaired and regularized following three floods in two years. Round posts 5.5m high with rectangular sawn longitudinal beams let into outside of posts and loft supported on round pole joists.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Five  Roof pitch approx. 40°. Loft not accessed.  Condition: ?  Date: ?  Loft enclosed with studs and boarded stud wall to west and corrugated iron on other 3 sides. Not accessible for internal inspection.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  Tall skillion to eaves height of main barn. Sawn beams rest on round posts.  Condition: Good  Date: Mid-19 <sup>th</sup> century but recently extensively renovated.  End skillion with lower floor level. Sawn rafters supported on beam		

ROOF CLADDING:	Corrugated steel
ROOF CLADDING.	Condition: Good
	Date: Recently replaced.
WALL CLADDING	Vertical timber slabs up to loft floor level, corrugated iron above and
WALL CLADDING	
	in gables. Condition: Good
ODENINGS	Date: Mid-19 <sup>th</sup> century but recently extensively renovated
OPENINGS	Skillion open on long side, barn has opening in central bay. Loft door
	at north end.
FLOORING (GROUND)	Concrete slab of recent construction with attempts to seal gaps
	around posts to prevent rot.
FLOORING (LOFT)	Plain edged boarding
FLOORING (SKILLION)	Concrete in skillion 1, earth in skillion 2
INTERNAL STRUCTURE	None
CHANGES FROM 2010?	Secondary posts removed, slabs added to walls. External stair
	removed. Internal spiral stair partially built.
DESCRIPTION BARN B	
MAIN BARN STRUCTURE	Two-storey barn orientated east-west with side skillion to south. It is
	in an unstable structural condition following three floods in two years
	and was unsafe to enter. Three rows of round posts with the central
	row of shorter posts supporting the upper floor.
	Condition: Poor
	Date: Late 19 <sup>th</sup> early 20 <sup>th</sup> century
NO. OF BAYS	Four
ROOF STRUCTURE	Roof pitch approx. 30° sawn rafters and battens suitable for iron,
	wind bracing.
	Condition: Poor
	Date: Late 19 <sup>th</sup> early 20 <sup>th</sup> century
LOFT	Not accessible for internal inspection.
	Condition: Poor
	Date: Late 19 <sup>th</sup> early 20 <sup>th</sup> century
SKILLION 1	Skillion extends to eaves height of main barn. Sawn beams rest on
	round posts.
	Condition: Poor
	Date: Late 19 <sup>th</sup> early 20 <sup>th</sup> century
ROOF CLADDING:	Corrugated steel
	Condition: Poor – storm damage
	Date: Early 20 <sup>th</sup> century?
WALL CLADDING	Corrugated iron
	Condition: Poor
	Date: Late 19 <sup>th</sup> early 20 <sup>th</sup> century
OPENINGS	One opening on north side
FLOORING (GROUND)	Concrete slab to northern half of main barn, remainder is earthen.
FLOORING (LOFT)	Irregular unfixed timbers including round poles
FLOORING (SKILLION)	Earthen
INTERNAL STRUCTURE	Short posts supporting mid-span of upper floor.
CURRENT USE	Disused.
CHANGES FROM 2010?	Storm and flood damage.
CHARGES I MOINI ZUIU;	Storm and nood damage.

#### **HISTORY**

William Snailham, ex-convict, was granted 30 acres (Portion 30, Parish Pitt Town) in the District of Mulgrave Place bounded on the west by the River Hawkesbury on 3 November 1794. He quickly disposed of the land. In 1800, William Snailham's 30 acres was held by Anthony Fenn Kemp. It is unclear when Kemp disposed of this grant. Kemp was heavily involved in trade, but most of his efforts were directed towards Tasmania. By 1812, the grant was in the hands of Henry Kable, who leased it along with Douglas' farm and Acres' farm (the two allotments to the north of Snailham's farm) for 10 years to his son, on 1 September 1812. On 14 August 1809, Kable had previously registered the transfer of numerous Hawkesbury farms to himself. Snailham's Farm was not listed under that name, but it may have been transferred by another person.

Henry Kable senior sold Snailham Farm of 30 acres to John Teale for £300 on 21 & 22 April 1826. John Teale of Windsor advertised the sale of Snailham's Farm of 30 acres, with a 'good dwelling-house and barn' on the land on 20 August 1831 along with 15 acres part of Acres' Farm.

On 2 January 1832, by a deed of feoffment, John Teale sold 15 acres, the northern part of Snailham Farm, to James Rochester as well as 15 acres part of Acres' farm for £220. It was bounded by land to the south, occupied by James Wilbow, being the other half of Snailham Farm.

By 1841, the southern half had been transferred to Henry Hudson of Windsor. Hudson had already purchased the northern half of the property in 1839, thus reuniting the original 30 acres of Snailham Farm.

Henry Hudson died in July 1848. On 23 August 1870, his son Robert Hudson, of Sydney, yeoman conveyed all 30 acres of Snailham Farm and two separate parcels of 15 acres parts of Acres' Farm to John Johnston, Portland Head, Hawkesbury River, farmer for £1,550. On 29 February 1896, John Johnston of Pitt Town, farmer gifted those parcels of land to his son Andrew George Johnston, Pitt Town, farmer.

Based on the physical evidence of the two existing barns, it appears that both barns were probably constructed during the period the property was owned by the Hudson family.

				ES

Grants Vol 1 p 112 (1)

C J Baxter, Musters and Lists New South Wales: and Norfolk Island 1800-1802, ABGR, Sydney, 1988, Entry AB072

M C Kemp, 'A F Kemp (1773? – 1868)', Australian Dictionary of Biography, Vol 2, pp 39-40

Old Register, Bk 4 page 3a, No 269; Bk 5 page 192, No 927; Bk 6 page 78, No 1450

Issue: March 2024

Old System Deed, No 532 Bk C Sydney Gazette, 20 Aug 1831 p 2 Real Property Application 17249

## STATEMENT OF SIGNIFICANCE

The barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms are of historical significance as surviving mid and late 19<sup>th</sup> century timber framed barns that are possibly associated with later landowners Henry Hudson Snr. and Jnr. They are surviving evidence of the long-term agricultural use of the land, first granted in 1794 to ex-convict William Snailham and known as Snailham's Farm.

The two barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms are of aesthetic significance as large, imposing structures, visible in broad scale views of the Hawkesbury River from the opposite bank along Wilberforce Road that make a strong contribution to the historical character of the locality.

Although extensively renovated and adapted (Barn A) and in poor condition (Barn B), both two storey barns retain evidence of their original construction dates and have the potential to provide further information into 19<sup>th</sup> century farming methods and construction techniques for

agricultural buildings. In the	eir overall forms and configurations, they are representative examples
	ed barn types found throughout the Hawkesbury City local government
area.	sa sam types round imoughout the nawkessary only roun government
ASSESSED SIGNIFICANCE	Local
TYPE	20001
CRITERIA A) HISTORICAL	The barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms are
	of historical significance as evidence of the long-term agricultural use
	of the land, first granted to ex-convict William Snailham in 1794,
	although he quickly disposed of the land. The barns are of historical
	significance as surviving from the mid and late 19 <sup>th</sup> century, although
	now altered, and appear to be associated with Henry Hudson Snr and
	Jnr, who owned the property in the 1840s through to 1870.
	Meets the criterion on a Local level.
CRITERIA B) HISTORICAL	The barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms are
ASSOCIATION	not associated with any persons of historical importance.
	Does not meet the criterion.
CRITERIA C)	The two barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms
AESTHETIC/TECHNICAL	are large, imposing structures, visible in broad scale views of the
•	Hawkesbury River from the opposite bank along Wilberforce Road
	that make a strong contribution to the historical character of the
	locality.
	Both two storey barns retain evidence of their original construction
	dates, although both are now clad in corrugated galvanised steel and
	Barn A has been extensively renovated and adapted.
	Meets the criterion on a Local level.
CRITERIA D)	The historic barns of the Hawkesbury district are appreciated by the
SOCIAL/CULTURAL	local community and others, being symbolic of the history of the
	agricultural development of the region, as evidenced by the
	numerous exhibitions, artworks, historical tours, heritage studies and
	heritage listings associated with these building types.
	Meets the criterion on a Local level.
CRITERIA E) RESEARCH	The forms of the barn, with skillions and lofts and retaining evidence
POTENTIAL	of their mid and late 19 <sup>th</sup> century construction dates have the
	potential to provide further information into 19 <sup>th</sup> century farming
	methods and construction techniques for agricultural buildings.
	Meets the criterion on a Local level.
CRITERIA F) RARITY	The barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms is
	not considered to be rare within the context of the Hawkesbury City
	local government area.
CDITEDIA C\	Does not meet the criterion.  The borns at No. 221 Bitt Town Bottoms Board Bitt Town Bottoms are
CRITERIA G)	The barns at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms are
REPRESENTATIVE	representative of the long history of agricultural development within the floodplains of the Hawkesbury River, which commenced in the
	late 18th century and continues today.
	The basic forms of the barns with gabled roofs, skillions and lofts are
	representative of the typical form of barn found throughout the
	district.
	Meets the criterion on a Local level.
INTEGRITY/INTACTNESS	Barn A- extensively renovated and adapted- Moderate to Little
INTEGRALIA INTACTIVESS	Barn B- Moderate
	שמווו ט- ואוטעכומנכ

### **IMAGES**



Caption: Barn A at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Pty Ltd

Date: May 2023



Caption: Barn A at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton Johnson & Partners Pty Ltd

Date: May 2023



Caption: Barn A at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

(interior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Pty Ltd



Caption: Barn B at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Pty Ltd

Date: May 2023




Caption: Barn B at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

(interior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Pty Ltd



Caption: Measured drawing of Barn A at No. 231 Pitt Town Bottoms Road, Pitt Town Bottoms

Copyright Owner: Graham Edds & Associates

ITEM DETAILS			
NAME	Single Storey Slab Barn with Loft		
OTHER/FORMER NAMES	Acres Farm		
ADDRESS	251 Pitt Town Bottoms Road, Pitt Town Bottoms		
LOCAL GOVT AREA	Hawkesbury		
PARISH	Pitt Town		
LOT/DP	Lot 16 DP 776017		
SHI No.	1743092/1740033		
EXISTING HERITAGE ITEM	Yes- Item I462		
RECOMMENDED MANAGEM			
MANAGEMENT SUMMARY	Not recommended for State heritage listing		
WANAGEWENT SOMMAN	Retain as local heritage item		
ITEM CLASSIFICATION	Netalli as local lieritage itelli		
ITEM TYPE	Built		
ITEM GROUP	Farming and Grazing		
ITEM CATEGORY	Barn		
	Balli		
DESCRIPTION	Υ		
CIRCA	Mid 19 <sup>th</sup> century		
PERIOD	,		
CURRENT USE	Storage		
FORMER USE	Barn		
LOCATION ON SITE	The barn is located to the south of the house and alongside the		
	Hawkesbury River. The barn has a skillion to the east and the river		
	on the west.		
MAIN CTRUCTURE	Access was not granted to inspect the barn internally.		
MAIN STRUCTURE	Single storey barn with loft. Single storey later skillion. Cross gable		
NO OF BAYS	inserted facing north to light loft space.		
NO. OF BAYS	Not accessed		
ROOF STRUCTURE	Not accessed		
LOFT	Not accessed		
SKILLION 1	Not accessed		
SKILLION 2	N/A		
ROOF CLADDING:	Corrugated iron		
WALL CLADDING	Corrugated iron. Weatherboards to gable ends.		
OPENINGS	Windows to loft.		
FLOORING (GROUND)	Concrete slab		
FLOORING (FIRST)	N/A		
FLOORING (LOFT)	Not accessed		
FLOORING (SKILLION)	Not accessed		
INTERNAL STRUCTURE	Not accessed		
OTHER (Fixings?)	Not accessed		

#### HISTORY

John Acres was granted 30 acres (Portion 29, Parish Pitt Town) in the district of Mulgrave Place bounded on the west by the River Hawkesbury on 3 November 1794. He also appears to have been known as Thomas Acres/Akers.

John Acres/Thomas Acres was transported for 7 years as part of the First Fleet and was emancipated in 1792.

The conveyance of a 30 acre farm from Thomas 'Akers' to Thomas Lewer for £180 was recorded on 27 May 1805. By 1810, the farm was held by Henry Kable. In 1810, 'William Henry' Kable leased Acres Farm to Miles Fieldgate, for 15 bushels of wheat per acre for 30 acres for four years. Henry Kable had previously registered the transfer of numerous farms on the Hawkesbury to him on 14 August 1809. Acres Farm was not listed under that name, but it may have been transferred by another person. In 1815, Henry Kable senior leased Acres Farm on two separate occasions to Henry Kable junior.

By a deed of feoffment of 30 April 1830, Henry Kable senior transferred 15 acres to John Teale bounded on the west by Snailham Farm now owned by John Teale, on the east by the remaining part of the 30 acres held by Henry Kable, on the north by the River Hawkesbury and on the south by a government Road for £150. The metes and bounds description is the same as appeared on the deed.

On 2 January 1832, by a deed of feoffment, John Teale transferred the 15 acres, part of Acres' Farm, to James Rochester for £220 along with 15 acres part of Snailham Farm. James Rochester conveyed those parcels to Lawrence May senior on 22 & 23 May 1832 for £265. Christopher May of Pitt Town conveyed the two parcels to Henry Hudson of Windsor on 30 & 31 January 1839 for £350.

Henry Hudson died in July 1848. On 23 August 1870, his son Robert Hudson, of Sydney, yeoman conveyed all 30 acres of Snailham Farm and two separate parcels of 15 acres parts of Acres' Farm to John Johnston, Portland Head, Hawkesbury River, farmer for £1,550. On 29 February 1896, John Johnston of Pitt Town, farmer gifted those parcels of land to his son Andrew George Johnston, Pitt Town, farmer.

It is assumed the barn was constructed by members of the May or Hudson families.

REFERENCES Grants Vol 1 p 109 (1)

REFERENCES	Grants Vol 1 p 109 (1)
	Old Register, Book 1 page 105 No 588
	Old Register, Bk 3 page 17, No 119
	Old Register, Bk 4 page 3a, No 269
	Old Register, Bk 6 page 78, No 1450
	Old Register, Bk 6 page 79, No 1451
	Old System Deed, No 530 Bk C
	Old System Deed, No 974 Bk D
	Old System Deed, No 723 Bk E
	Old System Deed, No 336 Bk P
	Old System Deed, No 545 Bk 121
	Old System Deed, No 768 Bk 573

### STATEMENT OF SIGNIFICANCE

The barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms is of historical significance as a surviving mid 19<sup>th</sup> century timber framed barn that is associated with John Acres who first obtained the land in 1794 and Lawrence May Snr and Henry Hudson, later owners who ran the property as a horse stud.

https://convictrecords.com.au/convicts/akers/thomas

Issue: March 2024

The large single storey barn (now clad in corrugated metal) with two lofts and rear skillion, makes a strong contribution to the historical character of the agricultural lands along Pitt Town Bottoms

Road and the Hawkesbury River floodplains. In its overall form and configuration, it is a representative example of an historic timber framed barn type found throughout the Hawkesbury City local government area.

The barn is potentially of technical significance for demonstrating mid  $19^{th}$  century construction methods for agricultural buildings and has the potential to provide further information into  $19^{th}$  century farming methods.

century farming methods.	Ι
ASSESSED SIGNIFICANCE	Local
TYPE	
CRITERIA A) HISTORICAL	The barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms is of
	historical significance as evidence of the long-term agricultural use
	of the land, first granted to ex-convict John Acres (Thomas Acres) in
	1794. Dating from the mid 19 <sup>th</sup> century, the barn appears to be
	associated with either Lawrence May senior or Henry Hudson, who
	separately owned the property in the 1830s to 1850s and who both
	used the land as a horse stud.
	Meets the criterion on a Local level.
CRITERIA B) HISTORICAL	The barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms is
ASSOCIATION	not associated with any persons of historical importance.
	Does not meet the criterion.
CRITERIA C)	The large single storey corrugated metal clad timber framed barn
AESTHETIC/TECHNICAL	with skillions, makes a strong contribution to the historical character
	of the agricultural lands along Pitt Town Bottoms Road and the
	Hawkesbury River floodplains.
	Meets the criterion on a Local level.
CRITERIA D)	The historic barns of the Hawkesbury district are appreciated by the
SOCIAL/CULTURAL	local community and others, being symbolic of the history of the
JOSIAL, COLI ONAL	agricultural development of the region, as evidenced by the
	numerous exhibitions, artworks, historical tours, heritage studies
	and heritage listings associated with these building types.
	Meets the criterion on a Local level.
CRITERIA E) RESEARCH	
POTENTIAL	The form of the barn, with skillion and loft has the potential to
POTENTIAL	provide further information into 19 <sup>th</sup> century farming methods and
	mid 19 <sup>th</sup> century construction techniques for agricultural buildings.  Meets the criterion on a Local level.
CDITEDIA E\ DADITY	
CRITERIA F) RARITY	The barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms is
	not considered to be rare within the context of the Hawkesbury City
	local government area.
CDITEDIA CI	Meets the criterion on a Local level.
CRITERIA G)	The barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms is
REPRESENTATIVE	representative of the long history of agricultural development
	within the floodplains of the Hawkesbury River, which commenced
	in the early 19 <sup>th</sup> century and continues today.
	The basic form of the barn with gabled roof, skillion and loft is
	representative of the typical form of barn found throughout the
	district.
	Meets the criterion on a Local level.
INTEGRITY/INTACTNESS	External- moderate integrity

### **IMAGES**



Caption: Barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton Johnson & Partners Pty Ltd






Caption: Barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Pty Ltd



Caption: Measured drawing of Barn at No. 251 Pitt Town Bottoms Road, Pitt Town Bottoms

Copyright Owner: Graham Edds & Associates

ITEM DETAILS			
NAME	Complex of Two Slab Barns with Lofts		
OTHER/FORMER NAMES	Dad and Dave's Turf Supplies		
ADDRESS	265 Pitt Town Bottoms Road, Pitt Town Bottoms		
LOCAL GOVT AREA	Hawkesbury		
PARISH	Pitt Town		
LOT/DP	Lots 8 & 9 DP 1079633		
SHI No.	1743093		
EXISTING HERITAGE ITEM?	Yes- Item No. I464 (SHI No. 1743093)		
RECOMMENDED MANAGEM			
MANAGEMENT SUMMARY	Recommend for State heritage listing- internal inspection required		
	to clarify condition and integrity.		
ITEM CLASSIFICATION	Retain as local heritage items.		
	Built		
ITEM CROUD			
ITEM GROUP	Farming and Grazing		
ITEM CATEGORY	Barn		
DESCRIPTION	V.		
CIRCA	Y		
PERIOD	Early 19 <sup>th</sup> century		
MODIFICATION/DATES	Barns 1 & 2 were linked in 2009.		
CURRENT USE	Unknown- potentially part residential		
FORMER USE	Barns		
LOCATION ON SITE:	Complex of two barns orientated in line north-south facing the eastern bank of the Hawkesbury River. In 2010 and 2023 access was denied to the site.  The following description is based on the inspection of 1991 by Graham Edds & Associates and by viewing the site from the road and riverside.		
DESCRIPTION BARN 1			
MAIN BARN STRUCTURE	Large single storey barn 16 x 6.5m on plan. Closely spaced round posts (1.3 – 1.6m centres) supporting rectangular beams to loft floor and square beams to roof eaves.  Condition: not known  Date: Early 19 <sup>th</sup> century		
NO. OF BAYS	Ten		
ROOF STRUCTURE	Gabled roof with 45° pitch and shingles under corrugated iron.  Condition: not known  Date: Early 19 <sup>th</sup> century		
LOFT	Converted to residential use for times of flood. Condition: not known Date: Early 19 <sup>th</sup> century structure, adaptation date not known.		
SKILLION 1	Western roof slope continues to form a steep skillion enclosing a mezzanine floor at the lower eaves level. Condition: not known Date: Early 19 <sup>th</sup> century		
SKILLION 2	Recent shallow pitched addition Condition: not known. Date: Not known.		

ROOF CLADDING:	Corrugated iron over timber shingles
ROOF CLADDING.	Condition: not known
	Date: Shingles early 19 <sup>th</sup> century
WALL CLADDING	Vertical timber slabs with weatherboard above and in gables.
	Condition: not known
	Date: Early 19 <sup>th</sup> century
OPENINGS	Dormer window inserted into western slope of loft roof plus
	windows in gable ends.
FLOORING (GROUND)	Timber floor structure indicated on 1991 plan drawing
FLOORING (LOFT)	Not known
FLOORING (SKILLION)	Not known
INTERNAL STRUCTURE	Not known
DESCRIPTION BARN 2	
MAIN BARN STRUCTURE	Single storey barn with loft 6 x 11m on plan with 3m end skillion.
	Closely spaced round posts (at 850mm centres) supporting
	rectangular beams to loft floor and roof eaves.
	Condition: not known
	Date: Early 19 <sup>th</sup> century
NO. OF BAYS	Eleven
ROOF STRUCTURE	Gabled roof with 45° pitch .
	Condition: not known
	Date: Early 19 <sup>th</sup> century
LOFT	Condition: not known
	Date: Early 19 <sup>th</sup> century structure, adaptation date not known.
SKILLION 1	Northern end skillion had slab walls with posts expressed on outside
	and slabs fixed to inside face of beam. Timber shingles remained in 2009.
	Condition: not known
	Date: Early 19 <sup>th</sup> century?
ROOF CLADDING:	Corrugated iron
NOO! CLADDING.	Condition: not known
	Date: not known
WALL CLADDING	Vertical slabs between posts, weatherboard above and in gables.
	Condition: not known
	Date: Early 19 <sup>th</sup> century
OPENINGS	Wide central openings in main barn for cart or carriage access.
	Dormer windows inserted into loft roof.
FLOORING (GROUND)	Timber floor indicated in 2009 report.
FLOORING (LOFT)	Not known
FLOORING (SKILLION)	Not known
INTERNAL STRUCTURE	Splayed boarding up to 1.8m internally.
HISTORY	

William Douglas (var. Douglass) was granted 30 acres (Portion 28, Parish Pitt Town) to be known as Douglas Farm lying on the east side of the Hawkesbury River in the District of Mulgrave Place on 3 November 1794. Today, No. 265 Pitt Town Bottoms Road is located on the whole of Portion 28 and the southern half of the adjacent land grant made to Joseph Wright, ex-convict, in 1794 (Portion 27, Parish Pitt Town).

William Douglas was an ex-convict, having been transported for 7 years and arrived in the colony as part of the First Fleet. Douglas died in 1838.

Christopher Watkin May held this grant, which he described as being 45 acres in his will of 31 January 1899, though it was found by a later survey to be 42 acres 2 roods 3½ perches.

It is not clear when Christopher Watkin May acquired this land. He was the son of Lawrence (alt. Laurence) May who was a significant landholder in the Hawkesbury district. In June 1845, Christopher Watkin May claimed in a court case to hold five farms across the district. Lawrence May had also purchased a number of farms in the Pitt Town district. It is possible that the current property was in the hands of Lawrence May and passed to his son Christopher Watkin May after his death or that Christopher Watkin May acquired in his own right. The large scale of the barns indicates the success and prosperity of the May family.

It is known that Christopher Watkin May was the owner of a town allotment (No. 26A Buckingham Street, Pitt Town) which also contains a large barn constructed in the late 19<sup>th</sup> century, possibly during May's period of ownership (1862-1879). Town barns were often relied on during times of flood when produce, livestock and equipment could be relocated from farm-lands and safeguarded on higher ground in the towns. This approach to the management of property was formalised via colonial era policy regarding land tenure when Governor Macquarie established inseparable links between the town allotments and farming lands. Christopher Watkin May left the land to trustees in his will to divide into two equal parts, leaving the southern part to his nephew, James Alfred May.

Christopher Watkin May died on 16 July 1900 and James Alfred May died on 1 September 1949, leaving instructions as to how to divide the land amongst his relatives.

At the November 1923 assessment by the Valuer General, improvements on 15 acres, part of Portions 27 and 28, held by Mrs Florence Gertrude May were described as cottages with attics, a detached kitchen plus 'slab sheds'. This probably relates to what is now Number 265 Pitt Town Bottoms Road. The adjoining 15 acres was described as part of Portion 28 held by Joshua May were described as including clearing and fencing as well as a 'bark hut'. This appears to be what is now known as Number 259 Pitt Town Bottoms Road.

_	_	Ξ	_	_	_		_	_	_
R	F	F	F	R	F	N	C	F٩	ς

Grants, Vol 1 No 108 (3)

Australian, 7 June 1845, p 1376

Windsor and Richmond Gazette, 7 Aug 1900, p 7

Valuer General, Valuation cards, State Archives of New South Wales, NRS

14466, 13/7923, No 2005 & 2006

#### STATEMENT OF SIGNIFICANCE

The barns at No. 265 Pitt Town Bottoms Road, Pitt Town Bottoms are of historical significance as surviving early 19<sup>th</sup> century barns still located on the original land grant made to ex-convict William Douglas in 1794 and for their associations with the May family, prosperous landowners in the Pitt Town district who obtained the land in the mid 19<sup>th</sup> century and continued to reside and work the land until at least the early 20<sup>th</sup> century. Charles Watkins May, who owned the land from c1845 to 1900, also held a town allotment in Pitt Town, which also contains a large late 19<sup>th</sup> century slab barn (26A Bathurst Street, Pitt Town).

Sited in the floodplains of the Hawkesbury River, the barns are located in a small complex with weatherboard cottage and mature trees that together make a strong contribution to the historical character of the agricultural lands along Pitt Town Bottoms Road. The overall form and configuration of both barns, with corrugated metal cladding and surviving timber slabs are good, large, representative examples of the historic barn type found throughout the Hawkesbury City local government area.

Although altered and potentially adapted for residential use, both of the barns are potentially rare as surviving early 19<sup>th</sup> century slab barns that remain in use, and potentially of technical

significance for retaining surviving evidence of early 19<sup>th</sup> century construction techniques including round timber posts closely spaced and shingled roofing. They also contain lofts that have been converted to residential and refuge areas during times of flood. Further research is required to determine their current condition and level of integrity, although both barns have been recorded as having high levels of integrity in 1991 and 2010

as having high levels of integrity in 1991 and 2010					
ASSESSED SIGNIFICANCE	State				
TYPE					
CRITERIA A) HISTORICAL	The barns at No. 265 Pitt Town Bottoms Road, Pitt Town Bottoms are of historical significance as evidence of the long-term agricultural use of the land, first established in 1794 by ex-convict William Douglas (var. Douglass), and as surviving, early 19 <sup>th</sup> century barns still located on their original land grant.  Meets the criterion on a State level.				
CRITERIA B) HISTORICAL	The barns have historical associations with William Douglas, a First				
ASSOCIATION	Fleet convict and original land grantee and with Charles Watkins May a prosperous land owner in the Pitt Town district and who owned the property from the mid 19 <sup>th</sup> century until at least the early 20 <sup>th</sup> century, together with an allotment above the flood plains in Pitt Town proper that still contains a mid 19 <sup>th</sup> century drying barn of large scale.  Meets the criterion on a Local level.				
CRITERIA C)	Located within a complex together with a weatherboard cottage and				
AESTHETIC/TECHNICAL  CRITERIA D)	mature trees sited above the floodplains of the Hawkesbury River, the two corrugated metal and timber slab clad barns make a strong contribution to the historical character of the agricultural landscape along Pitt Town Bottoms Road.  Based on previous inspections, and although altered, both barns are potentially of technical significance, retaining evidence of early construction techniques associated with agricultural buildings and timber slab construction, including closely spaced round posts and shingled roofs. One barn is considered very large, an indication of the prosperity of the owners.  Meets the criterion on a Local level.  The historic barns of the Hawkesbury district are appreciated by the				
SOCIAL/CULTURAL	local community and others, being symbolic of the history of the				
	agricultural development of the region, as evidenced by the numerous exhibitions, artworks, historical tours, heritage studies and heritage listings associated with these building types.  Meets the criterion on a Local level.				
CRITERIA E) RESEARCH	The forms of the barns, with skillions and lofts and retaining				
POTENTIAL	evidence of 19 <sup>th</sup> century construction techniques, have the potential to provide further information into 19 <sup>th</sup> century farming methods. <i>Meets the criterion on a Local level.</i>				
CRITERIA F) RARITY	The barns at No. 265 Pitt Town Bottoms Road, Pitt Town Bottoms are				
	potentially rare within the context of the Hawkesbury City local government area, for the extent of the surviving evidence of early construction techniques and as surviving early 19 <sup>th</sup> century timber slab barns that remain in use on their original 1794 land grant. One of the two being an exceptionally large barn. The historical links between 265 Pitt Town Bottoms Road and the town allotment in Pitt Town proper, which still retains its mid 19 <sup>th</sup> century large scale drying				

	barn, both being owned by Charles Watkins May, enhances the rarity			
	of this property and the barns.			
	Meets the criterion on a State level.			
CRITERIA G)	The barns at No. 265 Pitt Town Bottoms Road, Pitt Town Bottoms are			
REPRESENTATIVE	representative of the long history of agricultural development within			
	the floodplains of the Hawkesbury River, which commenced in the			
	early 19 <sup>th</sup> century and continues today.			
	The basic forms of the barns with gabled roofs, skillions and lofts are			
	representative of the typical form of barn found throughout the			
	district.			
	Meets the criterion on a Local level.			
INTEGRITY/INTACTNESS	Unknown- assumed moderate to high			

### **IMAGES**



Caption: Barns at No. 265
Pitt Town Bottoms Road,
Pitt Town Bottoms
Photographer: C. Edds

Copyright Owner: Grahams Edds

& Associates Date: 2009



Caption: Barn B at No. 265 Pitt Town Bottoms Road, Pitt Town Bottoms Photographer: C. Edds

Copyright Owner: Grahams Edds

& Associates Date: 2009




Caption: Barn A at No. 265
Pitt Town Bottoms Road,
Pitt Town Bottoms
Photographer: C. Edds

Copyright Owner: Grahams Edds

Issue: March 2024


& Associates
Date: 2009



Caption: Measured drawing of Barn A at No. 265 Pitt Town Bottoms Road, Pitt Town

Bottoms


Copyright Owner: Graham Edds & Associates



Caption: Measured drawing of Barn A at No. 265 Pitt Town Bottoms Road, Pitt Town

**Bottoms** 

Copyright Owner: Graham Edds & Associates



Caption: Measured drawing of Barn B at Noo. 265 Pitt Town Bottoms Road, Pitt

**Town Bottoms** 

Copyright Owner: Graham Edds & Associates

ITEM DETAILS		
NAME	Single Storey Slab Barn with Loft and Skillion	
OTHER/FORMER NAMES	-	
ADDRESS	283 Pitt Town Bottoms Road, Pitt Town Bottoms	
LOCAL GOVT AREA	Hawkesbury	
PARISH	Pitt Town	
LOT/DP	Lot 102 DP 1154658	
SHI No.	1743094	
EXISTING HERITAGE ITEM?	N	
RECOMMENDED MANAGEMENT		
MANAGEMENT SUMMARY	Not recommended for State or local listing	
ITEM CLASSIFICATION		
ITEM TYPE	Built	
ITEM GROUP	Farming and Grazing	
ITEM CATEGORY	Barn	
DESCRIPTION		
CIRCA	Υ	
PERIOD	Late 18 <sup>th</sup> to mid 19 <sup>th</sup> century	
FORMER USE	Barn	

2023: This barn has substantially collapsed. Unsalvageable and unsafe.

The physical description below is an extract from the 'Pitt Town Slab Barn Study', 1991, by Graham Edds and Associates.

High single storey slab barn with loft and lower level skillion on one longitudinal side. Some timber slabs remain on the lower skillion wall area and remnants of spaced slats on the opposite longitudinal wall. Horizontal boarding in dilapidated condition line the loft wall areas. Roof areas are gabled and lined with corrugated iron. External access door - no stairs remain. Independent floor structure remains at ground floor level. (Stumps and bearers). Central area of barn 12.9m x 5.5m. Probably used for drying of rural produce. Located on land below the 1 in 100 year flood level.

# Structure:

Post in ground at 1.7m centres extending into loft for roof structure. Remains of floor at ground level. Timber rounds used exclusively for posts, floor joists and roof framework. Timber stud framing used for loft wall frame between posts and at gable end.

# STATEMENT OF SIGNIFICANCE

The remains of the slab barn at 283 Pitt Town Bottoms Road is located on Portion 27 Parish Pitt Town, associated with ex-convict Joseph Wright's land grants promised in 1794. Joseph Wright was one of the signatories of the first Hawkesbury petition of December 1799 January 1800 over grain prices.

A tall early slab barn used primarily for drying produce and associated with early farming of the Hawkesbury district. An indicator of an early barn structure previously containing a raised floor

Issue: March 2024

INTEGRITY/INTACTNESS Substantially collapsed. Unsalvageable and unsafe.

# **IMAGES**



Caption: Barn at 283 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: LSJ Copyright Owner: Lucas Stapleton Johnson & Partners

Pty Ltd

Date: May 2023:




Caption: Barn at 283 Pitt Town Bottoms Road, Pitt Town Bottoms

(exterior)

Photographer: LSJ Copyright Owner: Lucas Stapleton Johnson & Partners

Pty Ltd

Date: May 2023:



Caption: Measured drawing of Barn at 283 Pitt Town Bottoms Road, Pitt Town

**Bottoms** 

Copyright Owner: Graham Edds & Associates

Date: May 2023

ITEM DETAILS			
NAME	Single Storey Slab Barn with Loft and End Skillion		
ADDRESS	303 Pitt Town Bottoms Road, Pitt Town Bottoms		
LOCAL GOVT AREA	Hawkesbury		
PARISH	Pitt Town		
LOT/DP	Lot 26 DP 1125833		
SHI No.	1743095		
EXISTING HERITAGE	N		
ITEM?			
RECOMMENDED MANAG	RECOMMENDED MANAGEMENT		
MANAGEMENT	Not recommended for State or local listing		
SUMMARY			
ITEM CLASSIFICATION	ITEM CLASSIFICATION		
ITEM TYPE	Built		
ITEM GROUP	Farming and Grazing		
ITEM CATEGORY	Barn		
DESCRIPTION			
CIRCA	Υ		
PERIOD	Late 18 <sup>th</sup> to mid 19 <sup>th</sup> century		
CURRENT USE	?		
FORMER USE	Barn		
LOCATION ON SITE	The barn is further hidden behind the overgrowth recorded in 1991.		
	This barn has not been inspected internally or fully recorded.		
INTEGRITY/INTACTNESS	Unknown		

2023: No access provided. Unable to be viewed from public road.

The physical description below is an extract from the 'Pitt Town Slab Barn Study', 1991, by Graham Edds and Associates.

### Description 1991:

Single storey with loft. Skill ion on short side. Located on land below the 1 in 100 year flood level.

Structure: Unable to obtain access to or photograph barn.

#### **HISTORY**

John Fenlow was granted 30 acres (Portion 26, Parish Pitt Town) on the River Hawkesbury in the District of Mulgrave Place on 3 November 1794. Fenlow shot dead his assigned servant David Lane on 4 July 1796, on suspicion that he had been consorting with his wife, Eleanor Byrnes. Local Aborigines assisted in locating Fenlow who was hiding on his grant. Fenlow was executed, apparently the only landholder to be executed before 1796.

On 21 September 1798, Jane Wheeler conveyed the grant to Thomas Gilberthorp. Thomas Gilberthorpe was recorded in 1802 as holding 30 acres in the district of Mulgrave Place acquired by purchase, with 14 acres cleared, and 11 acres in wheat with 1 acre in maize. Thomas Gilberthorpe advertised for two Sawyers to 'cut Timber for Building contiguous to Pitt Town on 11 May 1811. Inquiries were to be directed to Gilberthorpe, 'Cottage Farm, Hawkesbury'. Thomas Gilberthorpe of Pitt Town was commended on 5 February 1814 for offering grain to the government when others are withholding in the hope of higher prices.

Gilberthorpe appears to have sold the grant in smaller parcels. On 19 February 1817, Thomas Gilberthorp conveyed an unspecified area of land to Mary Nelson. In the 1830s and 1840s, different parts of Fenlow's grant were sold to Thomas Chaseling. On 14 November 1838, Mary Nelson sold an unspecified area to Thomas Chaseling. Later documentation suggests that this comprised 15 acres. Subsequently, on 14 October 1844, Constantine Molloy and Sarah Molloy sold

8 acres to Thomas Chaseling. Charles and Maria Kipper sold another part of 10 acres to Thomas Chaseling on 12 December 1857. The 15 acres sold by Mary Nelson to Chaseling is the site of 303 Pitt Town Bottoms Road.

A press report of 15 November 1859 of a master and servant case involving Thomas Chaseling, Pitt Town referred to taking a horse out of the stable.

	in garage out or the stable.
REFERENCES	Grants Vol 1 p 109 (3)
	Jan Barkley-Jack, Hawkesbury Settlement Revealed, pp 329-330
	C J Baxter, Musters and Lists New South Wales: and Norfolk Island 1800-
	1802, ABGR, Sydney, 1988, entry AG382
	Deposited Deeds Receipt 18997, Land Registry Services, New South
	Wales
	Sydney Gazette, 11 May 1811, p 1
	Sydney Gazette, 5 Feb 1814, p 1
	<i>SMH</i> , 15 Nov 1859 p 3
	Old System Deed, No. 413 Bk 75
	, · · · ·

ITEM DETAILS	
NAME	Single Storey Slab Barn with Loft and Skillions
ADDRESS	313 Pitt Town Bottoms Road, Pitt Town Bottoms
LOCAL GOVT AREA	Hawkesbury
PARISH	Pitt Town
LOT/DP	Lot 1 DP 778704
SHI No.	1743096
EXISTING HERITAGE ITEM?	Yes- Item No. I466 (Heritage Item No. 1740036)
RECOMMENDED MANAGEM	
MANAGEMENT SUMMARY	Not recommended for State listing. Site inspection required into
	condition and integrity.
	Retain as local heritage item.
ITEM CLASSIFICATION	
ITEM TYPE	Built
ITEM GROUP	Farming and Grazing
ITEM CATEGORY	Barn
DESCRIPTION	
CIRCA	Υ
PERIOD	Late 19 <sup>th</sup> or early 20 <sup>th</sup> century (based on roof pitch, use of slabs and
	corrugated iron, although would benefit from further investigation)
MODIFICATION/DATES	Unsympathetic additions to eastern side. Changes from 2010-
-	Unknown
CURRENT USE	Dwelling
FORMER USE	Barn
LOCATION ON SITE:	The barn runs north-south alongside weatherboard house and is
	close to northern site boundary approximately 230m from eastern
	bank of Hawkesbury River
	In 2010 and 2023: Access was denied to the site. This description is
	based on previous inspection in 1991 by Graham Edds & Associates
	and viewing the site from the road.
MAIN BARN STRUCTURE	Single storey barn 10.6 x 6m on plan with round posts supporting
	loft and gabled roof. The northern roof slope continues to enclose a
	skillion which is hipped and wraps around the western end.
	Condition: Good
	Date: Late 19 <sup>th</sup> or early 20 <sup>th</sup> century
NO. OF BAYS	Six
ROOF STRUCTURE	Roof pitch approximately 30°.
NOO! SINGERONE	Condition: Not known
	Date: Late 19 <sup>th</sup> or early 20 <sup>th</sup> century
LOFT	Loft has a door and window at the northern end and a window in
1011	the southern end. It contains a loft floor at eaves level.
	Condition: Not known
	Date: Late 19 <sup>th</sup> or early 20 <sup>th</sup> century
SKILLION 1	Skillion is 3m wide and is supported on round posts and clad with
SKILLION I	vertical timber slabs.
	Condition: Not known
	Date: Late 19 <sup>th</sup> or early 20 <sup>th</sup> century
BOOL CLADDING:	
ROOF CLADDING:	Condition: Moderate
	Condition: Moderate.
	Date: Late 19 <sup>th</sup> or early 20 <sup>th</sup> century

WALL CLADDING	Vertical timber slabs with weatherboards to loft level and gables.
	Condition: Moderate
	Date:
OPENINGS	Main ground floor opening is positioned centrally on western side
FLOORING (GROUND)	Not known
FLOORING (LOFT)	Not known
FLOORING (SKILLION)	Not known
INTERNAL STRUCTURE	Not known
HISTORY	

John Fenlow was granted 30 acres (Portion 26, Parish Pitt Town) on the River Hawkesbury in the District of Mulgrave Place on 3 November 1794. Fenlow (vars. Fendlow) was sentenced to transportation for 7 years and arrived in the colony in 1788 as part of the First Fleet.

Fenlow shot dead his assigned servant David Lane on 4 July 1796, on suspicion that he had been consorting with his wife, Eleanor Byrnes. Local Aborigines assisted in locating Fenlow who was hiding on his grant. Fenlow was executed, apparently the only landholder to be executed before 1796.

The subsequent history of the grant is unclear until the 1840s. On 21 September 1798, Jane Wheeler conveyed the grant to Thomas Gilberthorp, an ex-convict who arrived in 1791. Thomas Gilberthorpe was recorded in 1802 as holding 30 acres in the district of Mulgrave Place acquired by purchase, with 14 acres cleared, and 11 acres in wheat with 1 acre in maize. Gilberthorpe advertised for two Sawyers to 'cut Timber for Building contiguous to Pitt Town on 11 May 1811. Inquiries were to be directed to Gilberthorpe, 'Cottage Farm, Hawkesbury'. Thomas Gilberthorpe of Pitt Town was commended on 5 February 1814 for offering grain to the government when others are withholding in the hope of higher prices.

Gilberthorpe appears to have sold the grant in smaller parcels. There is no information currently available about the history of this part of the grant for the following three decades.

On 7 April 1857, by a deed of Release, Thomas Miles of Pitt Town, farmer and Abraham Easterbrook of Pitt Town, farmer conveyed 10 acres to John Davis of Pitt Town, farmer. Davis had commenced legal action to obtain possession of this land, which he claimed was illegally held by Miles and Easterbrook. They agreed to convey the land for £100. The 10 acres was described as part of John Fenlow's grant, bounded on the north by the River Hawkesbury in the rear by the land originally held by William Hall, but then by James Dunstan, on the north east by Charles Kipper's other part of Fenlow's portion, on the south east by Thomas Chaseling's land then occupied by James Dunstan. This description was subsequently linked to more recent deeds regarding this parcel of land.

The *Hawkesbury Pioneer Register*, 1994 edition, noted that Abraham Easterbrook was the son-inlaw of Thomas Miles. Thomas Miles died on 26 April 1857, aged 84, after choking on a piece of meat.

On 12 January 1872, John Davis, senior, of Pitt Town, farmer conveyed this land to John Davis, junior of Pitt Town, farmer. It appears that the property remained in the hands of the Davis family until the mid  $20^{th}$  century.

Based on the known physical evidence, the barn appears to have been constructed by the Davis family.

REFERENCES	Grants Vol 1 p 109 (3)	
	Jan Barkley-Jack, Hawkesbury Settlement Revealed, pp 329-330	

C J Baxter, <i>Musters and Lists New South Wales: and Norfolk Island 1800-1802</i> , ABGR, Sydney, 1988, entry AG382
Sydney Gazette, 11 May 1811, p 1
Sydney Gazette, 5 Feb 1814, p 1
Sydney Morning Herald, 29 April 1857, p 3
Old System Deed, No 646 Bk 48
Old System Deed, No 254 Bk 129
Old System Deed, No 347 Bk 2654
Old System Deed, No 109 Bk 3137
Hawkesbury Pioneer Register, 1994, p 126

# STATEMENT OF SIGNIFICANCE

The barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms is of historical significance as a surviving late 19<sup>th</sup> to early 20<sup>th</sup> century barn and is representative of the long term agricultural use of the land, first granted in 1794 to ex-convict John Fenlow in 1794.

Sited above the floodplains of the Hawkesbury River, the barn is located in a small complex with weatherboard cottage and mature trees that together make a strong contribution to the historical character of the agricultural lands along Pitt Town Bottoms Road. The overall form and configuration of the barn, with corrugated metal cladding and surviving timber slabs is good representative example of the historic barn type found throughout the Hawkesbury City local government area.

The barn is potentially of technical significance for retaining surviving evidence of late 19<sup>th</sup> to early 20<sup>th</sup> century construction techniques, however, further research is required to determine its current condition and level of integrity.

ASSESSED SIGNIFICANCE TYPE	Local
CRITERIA A) HISTORICAL	The barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms is of historical significance as evidence of the long-term agricultural use of the land, first established in 1794 by ex-convict John Fenlow and as a surviving, late 19 <sup>th</sup> to early 20 <sup>th</sup> century barn.  Meets the criterion on a Local level.
CRITERIA B) HISTORICAL ASSOCIATION	The barn has historical associations with John Davis and his descendants. The Davis family obtained the property in the mid 19 <sup>th</sup> century and appear to have retained ownership until the mid 20 <sup>th</sup> century.  Meets the criterion on a Local level.
CRITERIA C) AESTHETIC/TECHNICAL	Located within a complex together with a weatherboard cottage and mature trees sited above the floodplains of the Hawkesbury River, the timber slab clad barn make a strong contribution to the historical character of the agricultural landscape along Pitt Town Bottoms Road.  Meets the criterion on a Local level.
CRITERIA D) SOCIAL/CULTURAL	The historic barns of the Hawkesbury district are appreciated by the local community and others, being symbolic of the history of the agricultural development of the region, as evidenced by the numerous exhibitions, artworks, historical tours, heritage studies and heritage listings associated with these building types.  Meets the criterion on a Local level.

CRITERIA E) RESEARCH	The form of the barns, with skillions and lofts has the potential to
POTENTIAL	provide further information into late 19 <sup>th</sup> century farming methods.
	Meets the criterion on a Local level.
CRITERIA F) RARITY	The barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms is potentially rare within the context of the Hawkesbury City local government area, as a surviving late 19 <sup>th</sup> to early 20 <sup>th</sup> century timber slab barns that remains in use.  Meets the criterion on a Local level.
CRITERIA G) REPRESENTATIVE	The barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms is representative of the long history of agricultural development within the floodplains of the Hawkesbury River, which commenced in the early 19 <sup>th</sup> century and continues today.  The basic form of the barn with gabled roof, skillions and lofts is representative of the typical form of barn found throughout the district.  Meets the criterion on a Local level.
INTEGRITY/INTACTNESS	Unknown

# **IMAGES**



Caption: Barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023



Caption: Barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023




Caption: Barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms

Photographer: S. Johnson

Copyright Owner: Lucas Stapleton

Johnson & Partners Date: May 2023



Caption: Measured drawing of barn at No. 313 Pitt Town Bottoms Road, Pitt Town Bottoms

Copyright Owner: Graham Edds & Associates

ITEM DETAILS	
NAME	Single Storey Slab Barn with Loft and Chimney- Demolished
ADDRESS	333 Pitt Town Bottoms Road, Pitt Town Bottoms
LOCAL GOVT AREA	Hawkesbury
PARISH	Pitt Town
LOT/DP	Lot 1 DP 774609
SHI No.	1743097
<b>EXISTING HERITAGE ITEM?</b>	N
RECOMMENDED MANAGEN	IENT
MANAGEMENT SUMMARY	Not recommended for State or local listing
ITEM CLASSIFICATION	
ITEM TYPE	Built
ITEM GROUP	Farming and Grazing
ITEM CATEGORY	Barn
DESCRIPTION	
CIRCA	Υ
PERIOD	Late 18 <sup>th</sup> to early 19 <sup>th</sup> century
MODIFICATION/DATES	[2010 inventory sheet]
	1991 to 2009
	The barn has developed a considerable lean due to the loss of
	structural integrity. Shortly after the site inspection a severe wind
	storm removed the remaining roof cladding.
CURRENT USE	Unknown
FORMER USE	Residence?
INTEGRITY/INTACTNESS	Unknown. Original barn appears to have been demolished.

2023: Access not permitted. Not inspected. The former barn/residence included in the 1991 study appears to have been demolished and replaced with a large, corrugated metal clad shed.

# [2010 inventory sheet]

The physical description below is an extract from the 'Pitt Town Slab Barn Study', 1991, by Graham Edds and Associates. This 2009 study has recorded changes/deterioration within the modification date field.

# Description 1991:

Single storey barn with loft and chimney. Slab walls and corrugated iron roof. Sandstone brick end wall and chimney collapsed. Previous battening for shingles evident. Characteristic lean. Covered in grape vine and wisteria. Central area of barn 9m x 4m. Located on land below the 1 in 100 year flood level.

#### Structure:

Post and beam structure. Posts extend into loft. Posts at close centres. Vertical slabs between posts to loft floor level. Horizontal splayed boarding to gable and sides above slabs.

# **HISTORY**

Peter Bond was granted 30 acres on the east side of the River Hawkesbury in the district of Mulgrave Place to be known as Parker Farm on 3 November 1794. By the late 1790s, Peter Bond's farm along with those of Edward Cunningham and John Owen had been acquired by Deputy Commissary James Williamson, which were managed for him by John Brenan. On 15 February 1803, James Williamson signed an agreement that John Brenan would supervise Williamson's Hawkesbury farms for £100. James Williamson leased three unnamed farms of cleared land to Laurence May on 1 August 1806. These were possibly the three farms of Bond, Cunningham and Owen.

On 26 & 27 January 1829, by a deed of Lease and release, Jane Williamson of Parramatta, widow, administrator of the estate of James Williamson deceased sold Parker farm of 30 acres granted to

Peter Bond to Patrick Mahony and Maurice Mahony of Pitt Town, farmers for £320. Patrick	
Mahoney signed his will on 28 December 1865 and died on 4 January 1866.	
On 26 May 1866, the trustees of the deceased estate of Patrick Mahoney, Windsor, yeoman,	
divided Peter Bond's grant amongst his devisees into 4 lots.	
REFERENCES	Grants, Vol 1 No 107
	Jan Barkley-Jack, Hawkesbury Settlement Revealed, pp 149, 333-4
	Old Register Volume 1 page 76 no 361
	Old Register Volume 1 page 139 No 1071
	Old System Deed, No 590 Bk B
	Old System Deed, No 696 Bk 98

ITEM DETAILS	
NAME	Single Storey Slab Barn with Loft and Ramp
OTHER/FORMER NAMES	Pittsmoor/ Owens Farm
ADDRESS	353 Pitt Town Bottoms Road, Pitt Town Bottoms
LOCAL GOVT AREA	Hawkesbury
PARISH	Pitt Town
	Lot 1 DP 569711
LOT/DP	
SHI No.	1743098
EXISTING HERITAGE ITEM?	Y- I467 (Heritage Item No. 1740037)
RECOMMENDED MANAGEM	
MANAGEMENT SUMMARY	Recommend for State heritage listing
	Retain as Local item
ITEM CLASSIFICATION	
ITEM TYPE	Built
ITEM GROUP	Farming and Grazing
ITEM CATEGORY	Barn
DESCRIPTION	
CIRCA	Υ
PERIOD	Early 19 <sup>th</sup> century
MODIFICATION/DATES	Mid 19 <sup>th</sup> (skillion) to Mid 20 <sup>th</sup> century (roof cladding)
CURRENT USE	Machinery store.
LOCATION ON SITE:	The barn is orientated north-south and is located halfway
	between road and east bank of Hawkesbury River (approximately
	140m east of river).
MAIN BARN STRUCTURE	A large and impressive single-storey barn 13.7m x 6.5m on plan
	with a loft supported on square adzed posts with unusual
	projecting eaves detail and longitudinal beams with trenched
	undersides to take post tenons and shaped ends of vertical slabs.
	Condition: Moderate
	Date: Early 19 <sup>th</sup> century
NO. OF BAYS	Eight
ROOF STRUCTURE	Roughly squared rafters at close centres, pegged to eaves beam
	and loft floor joists. Most of the original shingle battens survive.
	Condition: Moderate
	Date: Early 19 <sup>th</sup> century
LOFT	Tightly laid timber floor boards on round joists with top and
	bottom surfaces adzed flat.
	Condition: Moderate
	Date: Early 19 <sup>th</sup> century
SKILLION 1	Skillion to southern end built of small section round timber
	rafters on sawn square beam bolted to round posts. There is no
	sign of shingle battens. Gables are clad in weatherboard.
	Condition: Moderate
	Date: Mid- late 19 <sup>th</sup>
ROOF CLADDING:	Corrugated galvanized iron.
	Condition: Moderate
	Date: Mid-20 <sup>th</sup> century?
WALL CLADDING	Vertical timber slabs, weatherboards to gable ends.
	Condition: Moderate.
	Date: Early 19 <sup>th</sup> century
	- , ,

OPENINGS	Central doorway opening to east side. Loft accessed via external
FLOORING (GROUND)	Earthen
FLOORING (LOFT)	Timber boarding
FLOORING (SKILLION)	Earthen
OTHER (Fixings?)	Unusual cantilevered eaves with pegged joints. Unusual trenched longitudinal edge beam to suit mortises on top of posts and to accept shaped ends of vertical timber slabs.
CHANGES FROM 2010?	Raked round posts have been added outside both long sides and bolted to longitudinal beams to buttress the barn. Ramp rebuilt.
FORMER USE	Barn
HISTORY	

The barn at No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms is located on part of a grant of 30 acres (Portion 24, Parish Pitt Town) made on 3 November 1794 to John Owen situate on the east side of the River Hawkesbury in the district of Mulgrave Place to be known as Owen Farm. Ex-convict John Owen had arrived in the colony as part of the First Fleet.

By 1800, John Owen's 30 acres at Mulgrave Place, was held by James Williamson, Commissary with 20 acres cultivated. By this time, Williamson owned 359 acres of land and 419 head of stock including 320 sheep, one of the largest flocks in the settlement. It appears that No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms was one of a number of properties owned by Williamson and it is assumed the property was farmed by tenants or employees.

James Williamson died in 1826. On 1 June 1830, his widow, Jane Williamson, of Parramatta, conveyed John Owen's 30 acre grant to Patrick Mahony, Pitt Town, farmer for £300. The deed recited that John Owen's grant, was previously owned by John Owen. It was then held by Robert Ledaway, and then by James Williamson. It had lately been occupied by Patrick Mahony as tenant, who was now purchasing the land.

By a conveyance of 13 June 1865, Patrick Mahoney, Windsor, farmer conveyed various parcels of land to Roger Ryan, North Richmond, farmer. The land was 100 acres in several parcels being 50 acres, 37 acres 30 perches and 12 acres 3 roods 10 perches. The last parcel of 12 acres 3 roods 10 perches is the one relevant to this site, being part of a grant to John Owen, commencing at the Hawkesbury River at the south west corner of Cunningham's 30 acres bounded on the north by that grant 37 chains 50 links and then on the east by a line 3 chains 47 Links, on the south by a line to the Hawkesbury River, 38 chains, and on the west by that river.

After the death of Roger Ryan, the property passed to Edward Ryan, Glebe, carrier. It was then known as Myall Farm, occupied by Mrs John Ryan.

Based on the physical evidence of the construction it is assumed the barn was built by James Williamson between 1800-26 or Patrick Maloney who owned the property from 1826 to 1865.

REFERENCES	Grants Vol 1 No 107
	C J Baxter, Musters and Lists New South Wales: and Norfolk
	Island 1800-1802, ABGR, Sydney, 1988, entry AE522; entry
	AB059, List of land held by government officials
	B H Fletcher, 'J Williamson (1758-1826)', Australian Dictionary of
	Biography, volume 2, 197, p 602
	C J Baxter, Musters of New South Wales and Norfolk Island 1805-
	1806, ABGR, Sydney, 1989, entry A3338
	Old System Deed, No 446 Bk C; No 798 Bk 98; No 756 Bk 959

# STATEMENT OF SIGNIFICANCE

The barn at No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms is of historical, aesthetic, technical significance and rarity on a State level as a surviving early 19<sup>th</sup> century barn of high integrity.

The large (8 bay) barn with ramp access to loft level is a distinctive element in the rural landscape of Pitt Town Bottoms Road and makes a strong contribution to the historical character of the locality. The ramp in particular is a distinctive feature related to its position adjacent to the Hawkesbury River, allowing easy transportation of stock, equipment and machinery into the loft in times of flood, an important advantage for properties located in the floodplains.

The barn is of technical significance for retaining evidence of its early 19th century construction and unusual detailing including adzed posts, projecting eaves with pegged joints, longitudinal beams with trenched undersides to take post tenons and shaped ends of vertical slabs, roughly squared rafters at close centres pegged to eaves beam and loft floor joists, surviving shingle battens and tightly laid timber floor boards on round joists with top and bottom surfaces adzed flat.

The barn at No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms is considered to be rare within the context of the Hawkesbury City local government area for its unusual detailing, large scale, and extent of surviving early 19<sup>th</sup> century fabric. Of particular note is the overhanging triangulated roof together with timber pegged joints and close spacing of posts suggesting a very early construction date (potentially in the first two decades of the 19<sup>th</sup> century).

ASSESSED SIGNIFICANCE TYPE	State
CRITERIA A) HISTORICAL	The large barn at No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms, is of historical significance as a surviving early 19 <sup>th</sup> century barn that remains substantially intact, and as evidence of the long-term agricultural use of the land since the late 18 <sup>th</sup> century.  Meets the criterion on a State level.
CRITERIA B) HISTORICAL ASSOCIATION	The property is associated with ex-convict John Owen who was granted the land, known as Owens Farm, in 1794; and with James Williamson, Commissary who owned the land between 1800 and 1826 as one of a number of land holdings and with Patrick Maloney, local farmer who owned the property from 1826 to 1865. It is not known which owner or tenant of the land in the early 19 <sup>th</sup> century was responsible for the construction of the barn.  Meets the criterion on a Local level.
CRITERIA C) AESTHETIC/TECHNICAL	The large (8 bay) barn with ramp access to loft level is of aesthetic significance as a distinctive element in the rural landscape of Pitt Town Bottoms Road and makes a strong contribution to the historical character of the locality.  The ramp is a distinctive feature related to its position adjacent to the Hawkesbury River, allowing easy transportation of stock, equipment and machinery into the loft in times of flood, an important advantage for properties located in the floodplains.
	The barn is of technical significance for retaining evidence of its early 19 <sup>th</sup> century construction and unusual detailing including

	adzed posts, projecting eaves with pegged joints, longitudinal
	beams with trenched undersides to take post tenons and shaped ends of vertical slabs, roughly squared rafters at close centres pegged to eaves beam and loft floor joists, surviving shingle battens and tightly laid timber floor boards on round joists with top and bottom surfaces adzed flat. Of particular note is the overhanging triangulated roof together with timber pegged joints and close spacing of posts suggesting a very early construction date (potentially in the first two decades of the 19 <sup>th</sup> century).
	Meets the criterion on a State level.
CRITERIA D) SOCIAL/CULTURAL	The historic slab barns and outbuildings of the Hawkesbury district are appreciated by the local community and others, being symbolic of the history of the agricultural development of the region, as evidenced by the numerous exhibitions, artworks, historical tours, heritage studies and heritage listings associated with these building types.
	Meets the criterion on a Local level.
CRITERIA E) RESEARCH POTENTIAL	The large, highly intact barn of unusual detailing with surviving evidence of its early 19 <sup>th</sup> century construction has high potential to provide further information into early 19 <sup>th</sup> century farming methods and construction techniques.
	Meets the criterion on a State level.
CRITERIA F) RARITY	The barn at No. 353 Pitt Town Bottoms Road, Pitt Town Bottoms is considered to be rare within the context of the Hawkesbury City local government area for its unusual detailing, large scale, and extent of surviving early 19 <sup>th</sup> century fabric.  Meets the criterion on a State level.
CRITERIA G) REPRESENTATIVE	The barn is representative of the long history of agricultural development within the floodplains of the Hawkesbury River and South Creek, which commenced in the late 18 <sup>th</sup> century and continues today.
	Its overall form with gabled roof, skillion, loft and timber slab wall cladding is representative of the typical form of barn found throughout the district.  Meets the criterion on a Local level.
INTEGRITY/INTACTNESS	High
INTEGRITI/INTACTIVE33	TIIGII

# **IMAGES**



Caption: Barn at No.353 Pitt Town Bottoms Road, Pitt Town Bottoms (exterior) Photographer: S. Johnson Copyright Owner: Lucas Stapleton Johnson & Partners

Pty Ltd

Date: May 2023



Caption: Barn at No.353 Pitt Town Bottoms Road, Pitt Town Bottoms (exterior) Photographer: S. Johnson Copyright Owner: Lucas Stapleton Johnson & Partners

Pty Ltd

Date: May 2023



Caption: Barn at No.353 Pitt Town Bottoms Road, Pitt Town Bottoms (interior of

skillion)

Photographer: S. Johnson Copyright Owner: Lucas Stapleton Johnson & Partners

Pty Ltd

Date: May 2023